

PLAN

S.N. 032-0023

S.N. 032-0023


DECK PATCHING SURVEY

TOTAL DECK AREA = 930.7 SQ. YDS.


TOTAL ESTIMATED DECK SLAB REPAIR AREA = 185 SQ. YDS.

DATE OF SURVEY: 08/10/2007

LEGEND



DECK SLAB REPAIR (PARTIAL)



DECK SLAB REPAIR (FULL DEPTH) TYPE II

NOTES

LENGTHS AND WIDTH OF REPAIR AREAS WERE MEASURED AS INDICATED ON THE PLAN DETAIL.

THE ENGINEER SHALL SOUND THE REPAIR AREAS AS INDICATED ON THE PLAN DETAILS TO DETERMINE EXACT LIMITS OF DECK SLAB REPAIR PRIOR TO THE CONTRACTOR BEGINNING DECK SLAB REPAIR OPERATIONS.

BILL OF MATERIAL

ITEM	UNIT	TOTAL
DECK SLAB REPAIR (PARTIAL)	SQ YD	161
DECK SLAB REPAIR (FULL DEPTH) TYPE II	SQ YD	24

1									
	FILE NAME =	USER NAME = \$USER\$	DESIGNED	~	RON WOODSHANK	REVISED	-	03/21/2008	Γ
-	\$FILEL\$		DRAWN	-	RON WOODSHANK	REVISED	-	03/21/2008	
		PLOT SCALE = \$SCALE\$	CHECKED	-		REVISED	-		
1		PLOT DATE = \$OATE\$	DATE	-		REVISED	~		ĺ

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

DECV	CV	CLAD	DEDAID	F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEE NO.	
U		OLAD	REP	AIR	846	(6B-1)I	GRUNDY	29	18
		···					CONTRACT	NO. 66	728
E:	SHEET NO. 1	OF 1 SHEETS	STA. 571+00.67	TO STA, 573+01,17	EED BOA	AD DIST NO BUINOIS FED AN	PRO IECT		